17

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0056	4th Crs	Shanthi layout
Unique Road No.	**Length of full Road(m)**	
13-W0056-9260	122.00	

Road Details

Road From	Road To
2nd main	Dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
135.00	5.20			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS		BS Slab		South

16

Left Slabs

Other Flow Direction Type	Length (m)	Average Width(m)
	135.00	0.60

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		South

Right

Other Flow Direction Type	Length (m)	Average Width(m)
	135.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	yes	BWSSB	yes
OFC		Manholes	4
Others			

Zone: DASARAHALLI Ward No: 13 Ward Name: Mallasandra Street ID: W0056

Date: 27/08/2016 Time: 12:48:45 RI 20160827124845 Page 1 of 2

15

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0053	NA	MALLASANDRA
Unique Road No.	**Length of full Road(m)**	
13-W0053-85544	93.00	

Road Details

Road From	Road To
W00042	END
Type of Road	**Other Road Type**

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
0.00	0.00			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

(12)

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	No Drain		Others		

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	No Drain		Others		

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	**BWSSB**
OFC	**Manholes**
Others	

Inspection Details

Number of Trees	0	**Date of Inspection**	06/09/2015
Name	Parameswariah	**Remarks**	

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

(12)

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	No Drain		Others		

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	No Drain		Others		

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.00

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	**BWSSB**
OFC	**Manholes**
Others	

Inspection Details

Number of Trees	0	**Date of Inspection**	06/09/2015
Name	Parameswariah	**Remarks**	

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.